


Multi-function tester

PAT. M 413965
PAT. ZL201120136573.9

Test Tweezer




PCB circuit
conductive test



Fuse open &
short check



Multimeter connection
become SMD probe clip



SMD or small component

LED lights test



Change Battery figure :

1. Pull out top cover
2. Replace battery
23AE 12V
3. Recover top cover

